

RELEASE NOTES

RELEASE NOTICE

This is the February 2024 release notice for **Oceaneering® C-NavX1** GNSS receiver firmware version 1.0.6.5

REVISION HISTORY

Revision	Release Date	Change Details	Author
D	6 - Feb - 2024	v1.0.6.5 firmware operational release	Ben Dean
C	02 - Nov - 2023	v1.0.5.1 firmware operational release	Ben Dean
B	22 - Sep – 2023	v1.0.5.1 firmware release in new global format	Ben Dean
A	10 - Aug - 2023	v1.0.5.1 firmware release	Ben Dean

RELEASE AUTHORIZATION

Title	Signature	Date
Russel Morton	<i>Russell Morton</i>	06 - Feb - 2024

PRECEDING DOCUMENT DETAILS

Revision	Release Date	Change Details	Author
2	18 - Jan - 2023	v1.0.4.1 firmware release	Ben Dean
1	28 - Jul - 2022	v1.0.2.3 firmware release	Ben Dean
0	14 – Jul - 2023	Initial Release	Ben Dean

Disclaimers:

C-Nav, C-Nav3050, C-Tides and C-Monitor are trademarks of Oceaneering International, Inc.

“This document is the property of Oceaneering International and may not be used for any purpose unless authorized in writing by Oceaneering and which, upon demand, shall be returned. For any queries, related to Warranty and Limitation of liability, please contact your Accounts Manager for more information.”



TABLE OF CONTENTS

1	OVERVIEW	3
2	REFERENCES	3
3	IMPORTANT NOTES	3
4	FIRMWARE CHANGES / IMPROVEMENTS.....	3
5	FIRMWARE ZIP FILE CONTENTS	4
6	SOFTWARE UPDATE APPLICATION	4
7	KNOWN ISSUES.....	5

1 OVERVIEW

This is the release notice for C-NavX1[®] GNSS receiver firmware version 1.0.6.5

This document describes the changes, improvements and the new features added since the previous formal release of version 1.0.5.1

2 REFERENCES

Document Number	Document Title
CNAV-MAN-061	C-NavX1 GNSS Receiver User Guide.
CNAV-MAN-062	C-NavX1 Firmware Update Installation Procedure.
CNAV-MAN-063	C-NavX1 RINEX Procedure.
CNAV-BUL-0002	C-NavX1 Age of Correction Data Bulletin.

3 IMPORTANT NOTES

- This firmware will only function in C-NavX1[®] GNSS receivers.
- Update the receiver with a consistent ensemble of firmware.
- Extract the ZIP file contents to a new folder to ensure that all the correct firmware and documentation are in one location and there is no mixing of old and new firmware.
- Always install the new firmware with the antenna connected and in an area, where the receiver can track satellites.
- **Always wait for 1 minute prior to power cycling the receiver after installing the firmware.**

4 FIRMWARE CHANGES / IMPROVEMENTS

- Fixed baud rate/NMEA output setting preservation after power cycle of the C-NavX1[®].
- C-NavX1[®] will no longer behave as a DHCP server.
- C-NavX1[®] remote UDP port no longer fixed to a local value.
- Fixed LTE Pending status loop when service not internal SIM not activated on the network.
- Internal logging reverted to binary format to enable improved QC analysis capability (users requiring RINEX files will need to send the binary files to C-Nav for conversion)
- Velocity North/East/Up fields populated in PVT1B message for display in the extended navigation menu in C-Controller.
- NMEA VTG / RMC Course over ground fields populated.
- Filter changes to resolve NMEA VTG CoG values.

5 FIRMWARE ZIP FILE CONTENTS

This C-NavX1® GNSS receiver firmware is distributed in a compressed ZIP file. The ZIP file includes the following contents:

Filename	Version	Comments
1.0.6.5.img.gz	1.0.6.5	Zipped firmware image
CNAV-MAN-062 (C-NavX1 Firmware Update Installation Procedure)	1	Firmware loading instructions
CNAV-RN-0006, Rev D (C-NavX1 Firmware Release Notice)	D	This document
CNAV-MAN-063 (C-NavX1 RINEX Procedure)	1	RINEX instructions
C-NavX1 Firmware Updater	1.0.1	Windows application for firmware loading
TPS2RIN RINEX Application	1.0.28.3459	Zipped executable

6 SOFTWARE UPDATE APPLICATION

This firmware has been tested and is intended to be used with the following versions of controller:

Software	Version	Tick off
C-Setup	9.3.0 and newer	<input checked="" type="checkbox"/>
C-Monitor QA/QC Software	9.3.0 and newer	<input checked="" type="checkbox"/>
C-NaviGator	9.3.0 and newer	<input checked="" type="checkbox"/>
C-Scape	9.3.0 and newer	<input checked="" type="checkbox"/>

Updates located on SharePoint C-Nav Software / Released Versions, in the corresponding software folders. At time of release on the public facing website.

7 KNOWN ISSUES

- Only one controller can be connected on COM ports and one on ETH ports simultaneously.
- Data output rate is fixed at 1Hz.
- Web-UI restricted for future use.
- Unable to connect to the C-NavX1® upon initial power up until first position fix.
- TXRXINFOA not correctly populated for USB port resulting in display of cumulative port usage rather than current.
- For C-NavX1 S/N 0229 or lower, there is a known error when restarting the C-NavX1 with the USB connected to a host whereby the C-NavX1 will not boot up. (USB needs to be disconnected prior to restart).
- VTG output copies the CMG (true) value to the CMG Magnetic value. The CMG magnetic should be a null field.