

## Industrial Battery Systems

### Handling

- Wear chemical-resistant gloves and eye protection when handling lead-acid batteries.
- Use non-conductive inspection tools and cover all conductive work surfaces of the battery with an insulating material.
- Conductive materials, such as jewelry, should not be worn.
- Cells should be moved in trays using pushcarts to prevent accidental drops.
- Overheating can occur when cells or batteries are dropped.
- Maintain ABC or BC fire extinguishers near the handling area.

