

# Energy Isolation

Verify isolation before work begins,  
and use specified life-protecting equipment

## Fatality Prevention Behaviors

You must:

- Isolate any source of energy from release
- Conduct testing to verify that energy is not present by testing

If you are the supervisor or person in charge of the work, you must:

- Ensure that personnel are trained and competent

